

ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ:(ਭਤੇਮ)ਸ਼ਾਖਾਂ ਤਲਵਾੜਾ

ਨੰਬਰ: 42

ਮਿਤੀ: 07-05-2024

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ
ਐਸ.ਡੀ.ਸਰਵਹਿੱਤਕਾਰੀ ਵਿਦਿਆ ਮੰਦਿਰ
ਸੀਨੀਅਰ ਸਕੈਡਰੀ ਸਕੂਲ ਤਲਵਾੜਾ
ਜਿਲ੍ਹਾ ਹੁਸ਼ਿਆਰਪੁਰ।

ਵਿਸ਼ਾ:- ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਫਾਰ ਦੀ ਯੀਅਰ 2024-25
ਹਵਾਲਾ:- ਆਪ ਦੇ ਦਫਤਰ ਦਾ ਪੱਤਰ ਨੰਬਰ 006/21040/24 ਮਿਤੀ: 10.04.2024

ਉਪਰੋਕਤ ਬਿਲਡਿੰਗ ਦਾ ਨਿੱਰੀਖਣ ਨਿਮਨਹਸਤਾਖਰ ਅਤੇ ਸਬੰਧਤ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ
Visually Check ਕੀਤਾ ਗਿਆ ਅਤੇ ਇਹ ਬਿਲਡਿੰਗ ਸਾਲ 2024-25 ਲਈ ਸੁਰੱਖਿਅਤ ਪਾਈ ਗਈ ਹੈ। ਅੱਗੇ ਤੋਂ
ਹੇਠ ਲਿਖਿਆਂ ਹਦਾਇਤਾਂ ਵੱਲ ਵਿਸ਼ੇਸ਼ ਧਿਆਨ ਦਿੱਤਾ ਜਾਵੇ:-

- (1) ਬਿਲਡਿੰਗ ਦੇ ਆਲੇ ਦੁਆਲੇ ਅਤੇ ਛੱਤਾਂ ਉਪਰ ਪਾਣੀ ਨਾ ਖੜ੍ਹਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ।
- (2) ਜੇਕਰ ਇਮਾਰਤ ਵਿੱਚ ਕਿਸੇ ਕਿਸਮ ਦੀ ਤਰੇੜ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗ੍ਹਾਂ ਨੂੰ ਤਰੁੰਤ ਖਾਲੀ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਉਸ ਦੀ ਰਿਪੋਅਰ ਤੁਰੰਤ ਕਰਵਾਈ ਜਾਵੇ।
- (3) ਕਿਸੇ ਕਿਸਮ ਦੀ ਉਸਾਰੀ ਵਿੱਚ ਵਰਤੇ ਗਏ ਮਟੀਰੀਅਲ ਦੀ ਜੁੰਮੇਵਾਰੀ ਸਬੰਧਤ ਸਕੂਲ ਦੀ ਹੋਵੇਗੀ।
- (4) ਨਾਲ ਨੱਥੀ ਨਕਸ਼ੇ ਤੋਂ ਇਲਾਵਾ ਜੇਕਰ ਆਪ ਵੱਲੋਂ ਵਾਧੂ ਉਸਾਰੀ ਕਰਨੀ ਹੋਵੇ ਤਾਂ ਉਸ ਦੀ ਮੰਨਜ਼ੂਰੀ ਇਸ ਮਹਿਕਮੇ ਤੋਂ ਲਈ ਜਾਵੇ।
- (5) ਡਾਇਰੈਕਟਰ ਜਨਰਲ ਸਕੂਲ ਸਿੱਖਿਆ ਵਿਭਾਗ ਪੰਜਾਬ ਅਤੇ ਸਟੇਟ ਪ੍ਰੋਜੈਕਟ ਸਰਵ ਸਿੱਖਿਆ ਅਭਿਆਨ ਦੇ ਪੱਤਰ ਨੰ: 75444 ਮਿਤੀ: 06-11-2009 ਮੁਤਾਬਿਕ ਸਕੂਲ ਵਿੱਚ ਅੱਗ ਬਝਾਉਣ ਵਾਲੇ ਝੰਤਰ ਚਾਲੂ ਹਾਲਤ ਵਿੱਚ ਰੱਖੇ ਜਾਣ। ਕਿਸੇ ਵੀ ਅਣਸੁਖਾਵੀ ਦੂਰਘਟਨਾ ਦੀ ਸਾਰੀ ਜੁੰਮੇਵਾਰੀ ਸਬੰਧਤ ਸਕੂਲ ਦੀ ਹੋਵੇਗੀ।

ਨੱਥੀ/-

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ:
(ਭਤੇਮ)ਸ਼ਾਖਾਂ ਤਲਵਾੜਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ:

ਮਿਤੀ:

ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ ਉਸਾਰੀ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ:(ਭਤੇਮ)ਸ਼ਾਖਾਂ ਮੁਕੇਰੀਆਂ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰ: 1424-25 ਮਿਤੀ: 26-07-2017 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾਂ ਦਿੱਤੀ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਨੱਥੀ/-

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ:
(ਭਤੇਮ)ਸ਼ਾਖਾਂ ਤਲਵਾੜਾ।

Date: 07-05-2024

Principal

S.D. Sarvahitkari Vidya Mandir Senior Secondary School Talwara District Hoshiarpur.

Subject:- Building Safety Certificate for the Year 2024-25

References:- 006/21040/24 Date: 10.04.2024

The above building was visually checked by the undersigned and the concerned Junior Engineer and this building has been found safe for the year 2024-25. Special attention should be paid to the following instructions:-

Water should not be allowed to stagnate around the building and on the roofs.

If any kind of crack appears in the building, then that place should be vacated immediately and its repair should be done immediately.

The responsibility of the material used in any kind of construction will be the responsibility of the concerned school.

If you want to do additional construction apart from the attached map, then its approval should be taken from this department.

As per the letter of Director General School Education Department Punjab and State Project Sarva Sikhyan Abhiyan No. 75444 dated: 06-11-2009, fire extinguishers should be kept in working condition in the school. The entire responsibility of any unfortunate accident will be the responsibility of the concerned school.

Sub Divisional Engineer

Construction Sub Divisional Office: A

Branch Talwara.

The following is sent to the Executive Engineer, Construction Division, L:N:V: (Bhatem) Branch, Mukerian, with reference to his Back Number No. 1424-25 dated 26-07-2017 for information.

Sub Divisional Engineer

Construction Sub Division, L:N:V: (Bhatem) Branch, Talwara.